Analysis of Air Crash Accident: Root Cause Anaylsis of IranAir Airlines Flight 1974- IR-277



Aliasghar Kazemiafshar^a, Derya Azık Özkan^b, & Türker Özkan^b ^a Department of Civil Engineering, & ^bDepartment of Traffic and Transportation Psychology MIDDLE EAST TECHNICAL UNIVERSITY



1. Accident Information

Date: 9 January 2011 Site: 10 km SW of Urmia,

IRAN 37°55′8″N 45°17′1″W

Aircraft type: Boeing 727-286

Operator: IranAir Airlines Flight Number: IR277

Crew: Fatalities 10/ Occupants: 11 **Total:** Fatalities 78 / Occupants: 105







7. References

2. History of the Accident

The flight IR-727 was departure from Tehran, IRAN to Urmia, IRAN on 9 January 2011 at approximately 18:30 after 2.5-hour delay and operated by IranAir. About 75 minutes after the takeoff (19:45) from Urmia International Airport, the airplane crashed the near Terman village about 8nm southeast of the airport (approximate position N37.558 E45.171) and broke up in six major parts. Of the 105 passenger on this flight, 78 dead (10 crew, 68 passenger) and 27(1 crew, 26 passenger) survived and airplane was destroyed. The airplane crash first because of human factor .Also there were some other factors reported in relation to crew members actions

3. Aim & Method

Therefore, the aim of this study is to investigate the flight IR-277 accident by root cause analysis to understand the main cause of the accident of IranAir Flight 277 in 2011. By the time of this research, the official report has not published. So, the information related to the accident was gathered from interview of survived passengers and unofficial CVR and FDR data report from some pilot's reliable websites. In order to collect the relevant information timeline method was used. The problems were detected by investigating relevant findings about accident. Lastly, problems related with accidents were analyzed by 5 Why technique and fishbone method.

4. Information Mapping (Timeline of the Accident) 19:42:?? 18:30 Speed is more than The airplane climb to 9050 feet, the ice buildup on the The first failure was 19:44:?? The airplane left the Tehran tandard landing speed occurred from pilot by 19:45:?? he copilot closed the Flap without after 2.5 hour delay because so they announced of airplane and ice parts sucks into the engine N1. And All the recordings stopped. of low visibility at the Miss-approach and Goe slop for VOR/DM lescent and crash speed increased destination airpor ILS Procedure 1 Both engines stopped 19:43:?? 19:43:?? 18:35. They forget to complete the procedure 19:45:?? They tried to Quick. Start two engines and The co-pilot controlled activated and crew try to increase Go-around, and they speed of air plane to prevent forget to turn on Anti-ice and restart engine but engine N2 failed

5. Problem Analysis(cond't) **Human factors** The cockpit crew working to control stick shaker and **Human factors** Human factors airplane speed so, they forget to complete the The captain breaks the safety flight rules The pilots and the crew calculated false glide checklist of Go-around and forget to turn on Anti-ice and allow copilot controlled air plane at slop for VOR/DME ILS Procedure 1 and they and continues ignition systems visibility under 1500m and slippery don't recognize the speed of airplane decrease until the moment the Sick Shaker alarm was human factor, because crew don't activated pilot was not let copilot control the irplane and wrong calculation in gild slop can be prevented by following flight root and policy. tton which is easily prevented by simple go-around checklist. Environmental factors Weather of Urmia airport was foggy and snow with low clouds Communication Factors and the landing runway was not clearly seen at the level at which The copilot without captain permission closed the The caption did not say emergency situation so the the descent started. flaps and increase the descending speed. cabin crew, so they did not tell to passengers to go Also ,the ILS inurement at Urmia airport for calculation visibility is old version to Emergency Brace position and have less accuracy than newer versions

5. Problem Analysis

The accident occur after 75 minutes of the take off and the crew could not understand the problem. The official report has not

published.					
Problems	Why?	Why?	Why?	Why?	Why?
Problem 1: Miss approach at first try	The copilot controlled the airplane and the captain controlled at the landing procedure at the end of the flight	Pilot want to train copilot, but it is against flight safety policy	The pilot use false gild slope, so the speed is decrease and the Stick shaker alarm activated	In order to control speed they increase speed	The speed is more than standard landing speed so they cancelled landing and announced miss approach and go around
Problem 2: Wrong decision from cockpit crew after Miss-approach	During Miss approach and Go around, stick shake alarm and controlling airplane speed were distracted them	Forget to complete checklist for Go around	Forget to active Anti-ice and Continues ignition .		
Problem 3: Weak crew management and communication	Copilot don not permit captain to close flaps	Captain do not tell the emergency situation to cabin crew to prepare passengers for crash(CRM was not applied properly)	The crew do not familiar to fly in the cold, snow and foggy weather	Weak communication between airplane and control tower, captain don not announced emergency situation to control tower	The speed is more than standard landing speed so they cancelled landing and announced miss approach and go around

6. Findings & Recommendations

To conclude; in order to identify the problems, different types of root cause analyses were performed. As a result, the apparent causes of this accident can be listed as:

- ➤ Human factor
- 1. Miss approach at first try
- 2. Wrong decision from cockpit crew after Miss-approach
- 3. Weak crew management and communication
- 1. Landing runway was not clearly seen at the level at which the descent started.
- 2. ILS inurement at Urmia airport for calculation visibility is old version and have less accuracy than newer versions

This accident was an important example for "Human Factors" subject. When these tables are carefully examined in terms of causes; different countermeasures and interventions can be applied to future safety practices. In order to reduce the possibility of human error, the relationships of human with other safety elements should be carefully examined and necessary precautions should be taken. For example; changing the company policy of safety; taking all the precautions and making all the controls repeatedly and not letting a takeoff if there is a problem out there; preventing any kinds of hierarchical relationships in the cockpit; giving the necessary importance to the training of the employees, updating the training programs according to the needs of the company and the conditions, repeating the education at specific time periods.

- ission (TC-JOC, A330-303). (2015). INVESTIGATION OF RUNWAY EXCURSION ACCIDENT OF TURKISH AIRLINES TC-JOC, A330-303, AT TIA, KATHMANDU, NEPAL ON 4th MARCH 2015. AT TIA, KATHMANDU, NEPAL ON 4th
- > Afshar, A., Hajyhosseinloo, M., Eftekhari, A., Safari, M., & Yekta, Z. (2013). A Report of the Injuries Sustained in Iran Air Flight 277 that Crashed near Urmia, Iran. Archives Of Iranian Medicine, Volume 15, Number 5. Crash: Iran Air B722 near Uromiyeh on Jan 9th 2011, impacted terrain during go-around. (2017). Avherald.com. Retrieved 14 June 2017, from http://avherald.com/h?article=435f1587

nappening of Stall condition

- Interstate aviation committee. (2017). Final report of 747-412f crash. Retrieved from http://reports.aviation-safety.net/2015/20150304-0_A333_TC-JOC.pdf
 Iran Air Flight 277. (2017). En.wikipedia.org. Retrieved 14 June 2017, from https://en.wikipedia.org/wiki/Iran_Air_Flight_277
- Matt Lillywhite and Paul Dyer, (2016), Root Cause Analysis Civil Aviation Authority.
- Naghdi, M., & Alizadeh, M. (2017). Civil Liability of Iran Air toward the Air Crash of Boeing 727, Tehran-Urmia Flight. JOURNAL OF CURRENT RESEARCH IN SCIENCE ISSN 2322-5009, (CODEN (USA): JCRSDJ).
- Ranter, H. (2017). ASN Aircraft accident Boeing 727-286 EP-IRP Urmia (Orumiyeh) Airport (OMH). Aviation-safety.net. Retrieved 14 June 2017, from https://aviation-safety.net/database/record.php?id=20110109-0